

## **Appendix 2-A: Asbestos Assessment Summary Table**

**ASBESTOS ASSESSMENT SUMMARY SPREADSHEETS**

**Project:** RASCO Recycling Facility  
2241 Route 22-Dover Plains, NY  
**Project Number:** 8211060

**Attn:** Matt Martin

Building	Floor/Area	Room ID	Homogeneous Area	Quantity	Friability	Condition	Asbestos (Y/N)	Notes
1 Main	First Floor	A33	Heater Unit	1 EA	F	Poor	Y	Assumed ACM
1 Main	Second Floor	F34	Oven Machine	1 EA	F	Poor	Y	Dangerous Not Accessible
1 Main	Second Floor	E35-39, F35-39	Not Assessed	-				Dangerous Not Accessible
1 Main	Throughout Walls	Perimeter Wall Windows	Gray Paint on Windows	9,400 SF	NF	Poor	Y	HA 04 31.9% Chrysotile
1 Main	Throughout Walls	Throughout	Fiberboard Strip around Window Perimeter	10,600 LF	F	Poor	Y	HA 05 1.4% Chrysotile
1 Main	First Floor	A07-A15, A30-31, C07, C09, D16, D03-D13, D16	Column Caulk	133 LF	NF	Poor	Y	HA 06 29.1% Chrysotile
1 Main	First Floor	A09, A13, B34, B35, C10-C12, D18, D29, F13, F17	Exhaust Stack Sealant	86 LF	F	Poor	Y	HA 22 4.8% Chrysotile
1 Main	First Floor	A15, A17, C07, C16	Column Filler	15 LF	NF	Poor	Y	HA 24 80% Chrysotile
1 Main	First Floor	A12	Corrugated Board	45 SF	F	Poor	Y	HA 28 50% Chrysotile
1 Main	First Floor	A15	Corrugated Roofing Debris	1 SF	F	Poor	Y	HA 28 50% Chrysotile
1 Main	First Floor	D19	Corrugated Roofing Debris	2 SF	F	Poor	Y	HA 28 50% Chrysotile
1 Main	First Floor	F19-Southeast Corner	Corrugated Roofing Debris	4 SF	F	Poor	Y	HA 28 50% Chrysotile
1 Main	First Floor	North Side	Corrugated Roofing Debris	2,000 SF	F	Poor	Y	HA 28 50% Chrysotile
1 Main	First Floor	West Extension Room	Corrugated Roofing Debris	648 SF	NF	Poor	Y	HA 28 50% Chrysotile
1 Main	Second Floor	North Side of Building	Corrugated Roofing Debris	3,420 SF	F	Poor	Y	HA 28 50% Chrysotile
1 Main	Exterior	Roof Throughout Main Building & West	Corrugated Roofing	78,100 SF	NF	Poor	Y	HA 28 50% Chrysotile
1 Main	Exterior	Perimeter of Building (10' Extension)	Corrugated Roofing Debris	16,300 SF	NF	Poor	Y	HA 28 50% Chrysotile
1 Main	First Floor	A21/E22 Stairwell	Transite Board	60 SF	F	Poor	Y	HA 29 57.1% Chrysotile
1 Main	First Floor	A33	Transite Shoes in Electrical Debris on Floor	1 SF	F	Poor	Y	HA 29 57.1% Chrysotile
1 Main	First Floor	A29	Window Caulk Debris	6 SF	NF	Poor	Y	HA 33 18.2% Chrysotile
1 Main	First Floor	D31	Window Caulk Debris	1 SF	NF	Poor	Y	HA 33 18.2% Chrysotile
1 Main	First Floor	C15	Gasket on Heater-White Paper	3 LF	F	Poor	Y	HA 39 26.7% Chrysotile
1 Main	First Floor	West Extension Room	Brown Asphalt Shingle	8 SF	NF	Poor	Y	HA 45 3.2% Chrysotile
1 Main	First Floor	D19	Brown Asphalt Shingle	2 SF	NF	Good	Y	HA 45 3.2% Chrysotile
1 Main	Second Floor	E12-F12	Tar on Ducting	24 SF	NF	Poor	Y	HA 47 7.8% Chrysotile
1 Main	First Floor	West Extension Room	Window Caulk	390 LF	NF	Poor	Y	HA 48 24.1% Chrysotile
1 Main	Exterior	Windows Throughout	White Window Caulk	2,200 LF	NF	Poor	Y	HA 48 24.1% Chrysotile
1 Main	Exterior	Throughout Exterior Sides	Building Caulk	4,850 LF	NF	Poor	Y	HA 50 27.9% Chrysotile
1 Main	Exterior	East Side Bay A01	Gray Caulk Wood Panel Caulk	24 SF	NF	Poor	Y	HA 51 4.8% Chrysotile
1 Main	Exterior	East & West Side Chimneys	Exterior Black Waterproofing	2,000 SF	NF	Poor	Y	HA 52 36.4% Chrysotile
1 Main	Exterior	East & West Side Chimneys	Exterior Fiberboard at Chimneys	-	NF	Poor	Y	HA 53 11.9% Chrysotile
1 Main	Exterior	North Side	Flashing Tar	3,100 SF	NF	Poor	Y	HA 54 34.5% Chrysotile
1 Main	Exterior	East & West Side Chimneys	Black Felt Paper	1,320 SF	NF	Poor	Y	HA 55 40% Chrysotile

## ASBESTOS ASSESSMENT SUMMARY SPREADSHEETS

**Project:** RASCO Recycling Facility  
2241 Route 22-Dover Plains, NY

**Project Number:** 8211060

**Attn:** Matt Martin

Building	Floor/Area	Room ID	Homogeneous Area	Quantity	Friability	Condition	Asbestos (Y/N)	Notes
1 Main	Exterior	East & West Side Chimneys	Gray Paint on Chimney Bases	2,250 SF	NF	Poor	Y	HA 56 38.2% Chrysotile
1 Main	First Floor	A22 Extension	Wrapped Paper Pipe Insulation	22 LF	F	Poor	Y	HA 57 36.4% Chrysotile
1 Main	Second Floor	E22 Room	Fire Door	1 EA	F	Good	Y	HA 59 66.7% Chrysotile
1 Main	First Floor	A27	White Woven Gasket on Heater	2 EA	F	Poor	Y	HA 60 80% Chrysotile
1 Main	First Floor	B14	White Woven Gasket on Heater	2 EA	F	Poor	Y	HA 60 80% Chrysotile
1 Main	First Floor	C15	Gasket Seal	20 LF	F	Poor	Y	HA 60 80% Chrysotile
1 Main	First Floor	D29	White Woven Gasket on Heater	2 EA	F	Poor	Y	HA 60 80% Chrysotile
1 Main	First Floor	D29	White Woven Gasket on Heater	1 EA	F	Poor	Y	HA 60 80% Chrysotile
1 Main	First Floor	D36	White Woven Gasket on Heater	1 EA	F	Poor	Y	HA 60 80% Chrysotile
1 Main	First Floor	A12	Fire Door	1 EA	F	Good	Y	HA 62 57.1% Chrysotile
1 Main	First Floor	A22 Stairwell	Fire Door	4 EA	F	Good	Y	HA 62 57.1% Chrysotile
1 Main	First Floor	A39 Stairwell	Fire Door	1 EA	F	Good	Y	HA 62 57.1% Chrysotile
1 Main	First Floor	D19	Fire Door	2 EA	F	Good	Y	HA 62 57.1% Chrysotile
1 Main	Second Floor	F01	Fire Door	2 EA	F	Good	Y	HA 62 57.1% Chrysotile
1 Main	Exterior	Throughout Windows	Window Glazing Compound	10,000 LF	NF	Poor	Y	HA 71 5.2% Chrysotile
1 Main	Exterior	East Flat Roof	Built Up Roof System	2,250 SF	NF	Poor	Y	Roof Flooded Could Not Sample
1 Main	Exterior	East Flat Roof	Roof Flashing	230 SF	NF	Poor	Y	Roof Flooded Could Not Sample
1 Main	Exterior	East Flat Roof	Silver Roof Paint	2,250 SF	NF	Poor	Y	Roof Flooded Could Not Sample
Bldg 2	Interior	South Kiln Area	Cementitious Board Debris	200 SF	NF	Poor	Y	HA 04 40% Chrysotile
Bldg 2	Exterior	Throughout	Window Glazing	6,228 LF	NF	Poor	Y	HA 06 12.8% Chrysotile
Bldg 2	Exterior	Throughout	Window Caulk	558 LF	NF	Poor	Y	HA 07 27.5% Chrysotile
Bldg 2	Interior	South Kiln Area West Kiln	West Kiln Rope Gasket Rectangular	50 LF	F	Poor	Y	HA 09 66.7% Chrysotile
Bldg 2	Interior	South Kiln Area East Kiln	East Kiln Fire Brick Mortar	1,950 SF	F	Poor	Y	HA 14 2% Amosite; 9.7% Chrysotile
Bldg 2	Exterior	Roof Throughout	Corrugated Cementitious Roof	16,700 SF	NF	Poor	Y	HA 19 26.7% Chrysotile
Bldg 2	Exterior	North Bay	Building Caulk	535 LF	NF	Poor	Y	HA 22 22.4% Chrysotile
Bldg 2	Exterior	Exterior East Side	Caulk above Door	14 LF	NF	Poor	Y	HA 29 8.6% Chrysotile
Bldg 2	Interior	Silo Bay	Breeching Insulation	400 SF	F	Poor	Y	HA 31 66.7% Chrysotile
Bldg 2	Interior	Silo Bay	Wrapped Paper Pipe Insulation-8"	10 LF	F	Poor	Y	HA 34 50% Chrysotile
Bldg 2	Interior	Silo Bay	Mudded Joint Packing on Wrapped Paper-8"	4 EA	F	Poor	Y	HA 35 28.6% Chrysotile
Bldg 2	Exterior	East Side on Ground	Roof Flashing Tar	10 SF	NF	Poor	Y	HA 37 18.8% Chrysotile
Bldg 2	Interior	North East Shed	Gasket on Fan Unit	1 EA	F	Poor	Y	HA 38 10.5% Chrysotile
Bldg 3	First Floor	Throughout	Window Caulk	208 LF	NF	Poor	Y	HA 04 15.2% Chrysotile
Bldg 3	First Floor	Main Bay	Building Caulk	25 LF	NF	Poor	Y	HA 05 19.8% Chrysotile
Bldg 3	Roof	Throughout	Roofing Shingle Debris (2nd Layer)	6,240 SF	NF	Poor	Y	HA 07 2.3% Chrysotile
Bldg 3	Roof	Throughout	Roofing Tar Paper Debris (3rd Layer)	6,240 SF	NF	Poor	Y	HA 08 2.6% Chrysotile
Bldg 3	First Floor	Main Bay-North End-Heater	Gasket-White	1 EA	F	Poor	Y	HA 09 80% Chrysotile
Bldg 3	Roof	Throughout	Lower Layer Roofing Shingle-Black	6,240 SF	NF	Poor	Y	HA 16 15.1% Chrysotile

## ASBESTOS ASSESSMENT SUMMARY SPREADSHEETS

**Project:** RASCO Recycling Facility  
2241 Route 22-Dover Plains, NY

**Project Number:** 8211060

**Attn:** Matt Martin

Building	Floor/Area	Room ID	Homogeneous Area	Quantity	Friability	Condition	Asbestos (Y/N)	Notes
Bldg 3	Roof	Throughout	Flashing Tar on Asphalt Roof (Top Layer)	6,240 SF	NF	Poor	Y	HA 17 40.5% Chrysotile
Bldg 3	First Floor	Main Bay-North End-Heater	Gasket 14" diameter	1 EA	F	Poor	Y	HA 18 44.4% Chrysotile
Bldg 3	First Floor	Throughout	Door Filler	17 LF	NF	Poor	Y	HA 20 27% Chrysotile
4 Soil Recycling	First Floor	01- Dirt Storage	Window Glazing Compound	6,828 LF	NF	Poor	Y	HA 03 1.6% Chrysotile
4 Soil Recycling	Exterior	West Façade	Gray Building Caulk	80 LF	NF	Poor	Y	HA 14 2.5% Chrysotile
4 Soil Recycling	Exterior	South Façade	Black Roof Tar	140 LF	NF	Poor	Y	HA 15 13.5% Chrysotile
Bldg 5	Exterior	Throughout Windows	Exterior Window Caulk	296 LF	NF	Poor	Y	HA 05 17.3% Chrysotile
Bldg 5	Interior	Interior (Collapsed)	Fire Doors	2 EA	NF	Fair	Y	Inaccessible due to Structural Instability-Assumed ACM
Bldg 6	First Floor	01	Fire Door	2 EA	NF	Good	Y	Assumed
Bldg 6	First Floor	01	Electrical Switch Gear	2 EA	NF	Good	Y	Assumed
Bldg 6	First Floor	07 Elevator	Elevator Components	1 EA	NF	Poor	Y	Assumed
Bldg 6	First Floor	07 Elevator	Elevator Doors	2 EA	NF	Poor	Y	Assumed
Bldg 6	First Floor	08 Elevator Machine Room	Fire Door	1 EA	NF	Good	Y	Assumed
Bldg 6	First Floor	08 Elevator Machine Room	Electrical Switch Gear	1 EA	NF	Good	Y	Assumed
Bldg 6	Second Floor	202	Fire Door	1 EA	NF	Good	Y	Assumed
Bldg 6	First Floor	01	Wrapped Paper Pipe Insulation	94 LF	F	Poor	Y	HA 01 66.7% Chrysotile
Bldg 6	First Floor	04	Wrapped Paper Pipe Insulation	28 LF	F	Poor	Y	HA 01 66.7% Chrysotile
Bldg 6	First Floor	01	Mudded Joint Packing	22 EA	F	Poor	Y	HA 02 80% Chrysotile
Bldg 6	First Floor	04	Mudded Joint Packing	3 EA	F	Poor	Y	HA 02 80% Chrysotile
Bldg 6	First Floor	10	Mudded Joint Packing	1 EA	F	Poor	Y	HA 02 80% Chrysotile
Bldg 6	First Floor	10	Aircell Pipe Insulation	23 LF	F	Poor	Y	HA 09 57.1% Chrysotile
Bldg 6	Exterior	North Façade	Exterior Window Glazing Compound	288 LF	NF	Poor	Y	HA 10 2.2% Tremolite
Bldg 6	Exterior	East Façade	Exterior Window Glazing Compound	336 LF	NF	Poor	Y	HA 10 2.2% Tremolite
Bldg 6	Exterior	West Façade	Exterior Window Glazing Compound	100 LF	NF	Poor	Y	HA 10 2.2% Tremolite
Bldg 6	Exterior	North Façade	Exterior Window Caulk	24 LF	NF	Poor	Y	HA 11 21.7% Chrysotile
Bldg 6	Exterior	East Façade	Exterior Window Caulk	200 LF	NF	Poor	Y	HA 11 21.7% Chrysotile
Bldg 6	Exterior	South Façade	Exterior Window Caulk	117 LF	NF	Poor	Y	HA 11 21.7% Chrysotile
Bldg 6	Exterior	West Façade	Exterior Window Caulk	200 LF	NF	Poor	Y	HA 11 21.7% Chrysotile
Bldg 6	Exterior	South Roof	Roof Flashing	384 SF	NF	Poor	Y	HA R04 3.1% Chrysotile
Bldg 6	Exterior	South Roof	Silver Paint on Flashing	384 SF	NF	Poor	Y	HA R05 11.3% Chrysotile
Bldg 6	Exterior	Center Roof	Corrugated Roof Decking	5,120 SF	NF	Poor	Y	HA R06 22.2% Chrysotile
Bldg 6	Exterior	North Built Up Roof	Corrugated Roof Decking Debris	80 SF	NF	Poor	Y	HA R06 22.2% Chrysotile
Bldg 6	Exterior	Center Roof	Black Roof Sealant	60 SF	NF	Poor	Y	HA R07 7.2% Chrysotile
Bldg 6	Exterior	North Roof	Felt Paper	5,120 SF	NF	Poor	Y	HA R09 1.7% Chrysotile
Bldg 6	Exterior	North Roof	Gray Building Caulk	10 LF	NF	Poor	Y	HA R10 10.4% Chrysotile
Administration	First Floor	06- Corridor	Electrical Switchgear	1 EA	NF	Good	Y	Assumed

## ASBESTOS ASSESSMENT SUMMARY SPREADSHEETS

**Project:** RASCO Recycling Facility  
2241 Route 22-Dover Plains, NY

**Project Number:** 8211060

**Attn:** Matt Martin

Building	Floor/Area	Room ID	Homogeneous Area	Quantity	Friability	Condition	Asbestos (Y/N)	Notes
Administration	Basement	Basement	Aircell Pipe Insulation and Mudded Joint Packing Debris	3,264 SF	F	Poor	Y	HA 01 & HA 02 Throughout
Administration	Basement	Basement	Aircell Pipe Insulation	400 LF	F	Poor	Y	HA 01 80% Chrysotile
Administration	Basement	Basement	Mudded Joint Packing	50 EA	F	Poor	Y	HA 02 57.1% Chrysotile
Administration	First Floor	Throughout	12"x12" Gray Floor Tile	2,582 SF	NF	Poor	Y	HA 03 2.3% Chrysotile
Administration	First Floor	03- Office	9"x9" Tan Floor Tile	225 SF	NF	Poor	Y	HA 10 20.3% Chrysotile
Administration	First Floor	Bathrooms	Transite Wall Panels	624 SF	NF	Fair	Y	HA 17 66.7% Chrysotile
Administration	Exterior	Windows Throughout	Exterior Window Glazing Compound	1940 LF	NF	Poor	Y	HA 22 8.7% Chrysotile
Boiler House	First Floor	01- Main	Mag Breeching Insulation	1,200 SF	F	Poor	Y	HA 01 66.7% Chrysotile
Boiler House	First Floor	01- Main	Mag Boiler Insulation	500 SF	F	Poor	Y	HA 02 80% Chrysotile
Boiler House	First Floor	01- Main, South Façade & East Façade	Aircell Pipe Insulation	176 LF	F	Poor	Y	HA 03 44.4% Chrysotile
Boiler House	First Floor	01- Main	Mudded Joint Packing	60 EA	F	Poor	Y	HA 04 80% Chrysotile
Boiler House	First Floor	01- Main	Transite Panel Debris	20 SF	NF	Poor	Y	HA 08 36.4% Chrysotile
Boiler House	Exterior	Roof	Transite Panels	1,500 SF	NF	Poor	Y	HA 08 36.4% Chrysotile
Boiler House	First Floor	01- Main	Fiberglass Pipe Insulation	60 LF	F	Poor	Y	HA 09 57.1% Chrysotile
Boiler House	First Floor	01- Main	Debris on Floor	1,360 SF	F	Poor	Y	HA 10 50% Chrysotile
Boiler House	First Floor	01- Main	Boiler Brick Grout	112 SF	NF	Poor	Y	HA 14 57.1% Chrysotile
Boiler House	Exterior	Exterior Throughout	Exterior Window Glazing Compound	1,008 LF	NF	Poor	Y	HA 15 4.3% Tremolite
Boiler House	Exterior	Exterior Throughout	Window Sill Caulk	84 LF	NF	Poor	Y	HA 16 32.4% Chrysotile
Chlorination Bldg	Interior	Walls Throughout	Drywall Joint Compound	515 SF	F	Poor	Y	HA 02 1.3% Chrysotile
Chlorination Bldg	Exterior	East, South, West Side Windows	Window Glazing Compound	52 LF	NF	Poor	Y	HA 05 2.3% Chrysotile
Concrete Foundation	NO ACM							
1-2 Connector West	First Floor	Main Room	Gasket on Heater	1 EA	NF	Fair	Y	Inaccessible-Approximately 15 Feet High with Debris located beneath-Assumed ACM
1-2 Connector West	Exterior	South Side	Window Glazing	72 LF	NF	Poor	Y	HA 08 2.5% Chrysotile
1-2 Connector West	Exterior	Roof	Roofing Asphalt	2,990 SF	NF	Poor	Y	HA 10 31.9% Chrysotile
1-2 Connector West	Exterior	Roof	Flashing Tar	92 SF	NF	Poor	Y	HA 12 23% Chrysotile
Fire Pumphouse	First Floor	01- Generator Room	Boiler	18 SF	NF	Poor	Y	Assumed
Fire Pumphouse	First Floor	01- Generator Room	Gaskets	15 EA	NF	Fair	Y	Assumed
Fire Pumphouse	Exterior	North Façade	Exterior Window Caulk	4 LF	NF	Poor	Y	HA 05 5.3% Chrysotile
Fire Pumphouse	Exterior	Roof	Built Up Roof System-Layer 1 Tar	600 SF	NF	Good	Y	HA 09 2.1% Chrysotile
Fire Pumphouse	Exterior	Roof	Built Up Roof System-Layer 2 Shiny Tar	600 SF	NF	Good	Y	HA 10 9.4% Chrysotile

## ASBESTOS ASSESSMENT SUMMARY SPREADSHEETS

**Project:** RASCO Recycling Facility  
2241 Route 22-Dover Plains, NY  
**Project Number:** 8211060

**Attn:** Matt Martin

Building	Floor/Area	Room ID	Homogeneous Area	Quantity	Friability	Condition	Asbestos (Y/N)	Notes
Lab	Interior	Southeast Room	Mudded Joint Packing	3,000 SF	F	Poor	Y	Assumed ACM; Basement Flooded-Debris Presumed Throughout
Lab	Interior	Throughout	Homosote Board	-	F	Poor	Y	Assumed; Inaccessible due to Structural Instability
Lab	Interior	Southwest Room	Wiring	-	NF	Poor	Y	Assumed; Inaccessible due to Structural Instability
Lab	Interior	Hall	Flooring Materials	3,000 SF	F	Poor	Y	Floor Covered with Moss, Debris-Assumed to be ACM
Lab	Exterior	Windows Throughout	Window Glazing Compound	1,704 LF	NF	Poor	Y	HA 01 6% Chrysotile
Lab	Exterior	Doors and Windows Throughout	Window/Door Caulk Compound	25 LF	NF	Poor	Y	HA 02 25% Chrysotile
Lab	Exterior	Windows Throughout	Window Ledge Caulk	140 LF	NF	Poor	Y	HA 03 30% Chrysotile
Lab	Interior	Southeast Room	Pipe Insulation	3,000 SF	F	Poor	Y	HA 10 66.7% Chrysotile; Basement Flooded-ACM Debris Presumed Throughout
Lab	Interior	Southeast Room	Window Glazing Compound	18 EA	NF	Poor	Y	Stored Windows on Floor at South Wall
Office / Oil House	Exterior	North, South & East Façades	Gray Window Caulk	30 LF	NF	Poor	Y	HA 01 2.6% Chrysotile
Office / Oil House	First Floor	Interior	Electric Wiring	-	NF	Good	Y	Assumed ACM
Red Tank	Exterior	North Side	Wrapped Paper Pipe Insulation	60 LF	F	Poor	Y	HA 01 80% Chrysotile
Red Tank	Exterior	North Side	Black Tar Paper Wrap	60 LF	F	Poor	Y	HA 02 2.4% Chrysotile
Shell Bldg	Ground	East Side	Tar Paper Debris	10 SF	NF	Poor	Y	HA 03 54.3% Chrysotile
South Silos	First Floor	North Room	Cementitious Switchgear	20 SF	NF	Fair	Y	HA 05 26.7% Chrysotile
South Silos	Exterior	East & West Facades	Building Caulk	160 LF	NF	Poor	Y	HA 08 18.9% Chrysotile
South Silos	Exterior	Throughout	Window Caulk	115 LF	NF	Poor	Y	HA 09 20.1% Chrysotile
South Silos	First Floor	South Room	Corrugated Cementitious Roofing Debris	4 SF	NF	Poor	Y	HA 12 44.4% Chrysotile
South Silos	Exterior	Upper Conveyor Area	Corrugated Cementitious Roofing	5,500 SF	NF	Poor	Y	HA 12 44.4% Chrysotile
South Silos	Exterior	West Side-Metal Duct	Vertical Metal Duct Seam Gasket-Orange	144 LF	F	Fair	Y	HA 13 57.1% Chrysotile
South Silos	Exterior	West Side-Metal Duct	Flashing Tar on Metal Duct	9 SF	NF	Fair	Y	HA 15 7.9% Chrysotile
Water Treatment	First Floor	01- Main Room	Electrical Switch Gear	1 EA	NF	Fair	Y	Assumed
Water Treatment	Exterior	Water Tower	Electrical Switch Gear	2 EA	NF	Fair	Y	Assumed
Water Treatment	Interior	01 - Main Room and 02 - Tank Room	Electrical Wiring	-	NF	Fair	Y	Assumed
Water Treatment	First Floor	01- Main Room-above Drywall Ceiling	Wrapped Paper Pipe Insulation	56 LF	F	Fair	Y	HA 08 57.1% Chrysotile
Water Treatment	Exterior	North Façade	Wrapped Paper Pipe Insulation	10 LF	F	Poor	Y	HA 08 57.1% Chrysotile
Water Treatment	Exterior	Water Tower	Wrapped Paper Pipe Insulation	20 LF	F	Poor	Y	HA 08 57.1% Chrysotile
Water Treatment	Exterior	North Façade	Black Pipe Insulation Canvas	10 LF	F	Poor	Y	HA 09 1.6% Chrysotile
Water Treatment	Exterior	Water Tower	Black Pipe Insulation Canvas	20 LF	F	Poor	Y	HA 09 1.6% Chrysotile

### ASBESTOS ASSESSMENT SUMMARY SPREADSHEETS

**Project:** RASCO Recycling Facility  
2241 Route 22-Dover Plains, NY  
**Project Number:** 8211060

**Attn:** Matt Martin

Building	Floor/Area	Room ID	Homogeneous Area	Quantity	Friability	Condition	Asbestos (Y/N)	Notes
Water Treatment	Exterior	Water Tower	Window Glazing Compound	18 LF	NF	Poor	Y	HA 10 27.7% Chrysotile
Water Treatment	Exterior	East Façade	Window Caulk	6 LF	NF	Poor	Y	HA 11 20.9% Chrysotile
Water Treatment	Exterior	West Façade	Window Caulk	24 LF	NF	Poor	Y	HA 11 20.9% Chrysotile
Weigh Station	NO ACM							