

Appendix 2-A: Site Photographs



1. Building A – Office



2. Building B




3. Building B and clay pipe near roof



4. Building C (Looking southwest)



5. Interior of Building C



6. Building C first floor and white precipitate



7. Building D (Looking north)



8. Building D (concrete block) and
Building E (northern end)



9. Building E (looking south)

ARCADIS




Cricket Valley Energy Center LLC
Dover, NY
Site Reconnaissance Photographs
June 1-3, 2009

10. Building E (northern end)



11. Building F (storage building)



12. Building G (with steel chimney)

ARCADIS



Cricket Valley Energy Center LLC
Dover, NY
Site Reconnaissance Photographs
June 1-3, 2009

13. Building H (with brick chimney)



14. Building I



15. Gas Holder



16. Collapsed Steel Building



17. Large Storage Tank and associated building



18. Water Tower and associated building



19. Drum and white material disposal near Wetland 2.



20. Swale and banks leading to Wetland 2.



21. Wetland 2, with tan sawdust material visible.



22. Drum and debris near edge of north wetlands.



23. Pump station near Swamp River.